

[illegible]

Deleted	9.	02001	Other	19040039 A02	10/11/2017	11/29/2017	\$0	\$650	\$0		I - Informal Settlement
---------	----	--------------	-------	--------------	------------	------------	-----	-------	-----	--	-------------------------

Accident Investigation Summary						
Summary Nr: 97408.015		Event: 06/19/2017		Employee Is Struck By A Lathe'S Power Track And Suffers Mult		
At 7:30 a.m. on June 19, 2017, an employee was repairing an Okuma MacTurn 550 CNC Lathe and removed the back panel to troubleshoot the problem. The employee was struck by the moving power track of the lathe and suffered multiple lacerations above the eye, nose, neck, and back. The employee also suffered bruising to the chest area. The employee was hospitalized and treated for his injuries.						
Keywords: struck by, chest, face, lockout/tagout, laceration, neck, machine guarding, lathe, contusion, back						
	Inspection			Degree	Nature	Occupation
1	1248549.015			Hospitalized injury	Cut/Laceration	Machinery maintenance occupations

UNITED STATES DEPARTMENT OF LABOR

Occupational Safety and Health Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 800-321-6742 (OSHA)
TTY
www.OSHA.gov

FEDERAL GOVERNMENT

White House
Severe Storm and Flood Recovery Assistance
Disaster Recovery Assistance
DisasterAssistance.gov
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

OCCUPATIONAL SAFETY AND HEALTH

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

ABOUT THE SITE

Freedom of Information Act
Privacy & Security Statement
Disclaimers
Important Website Notices
Plug-Ins Used by DOL
Accessibility Statement